



[4910-13-P]

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**14 CFR Part 39**

**[Docket No. FAA-2012-0598; Directorate Identifier 2012-CE-017-AD]**

**RIN 2120-AA64**

**Airworthiness Directives; HPH s. r.o. Sailplanes**

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for all HPH s. r.o. Models 304C, 304CZ, and 304CZ-17 sailplanes. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as the lack of a drain hole in the elevator control rod, which may allow water to accumulate in the control rod and lead to possible corrosion. This condition could cause the elevator control rod to fail, which could result in loss of control of the sailplane. We are issuing this proposed AD to require actions to address the unsafe condition on these products.

**DATES:** We must receive comments on this proposed AD by [INSERT DATE 45 DAYS AFTER DATE OF PUBLICATION IN THE FEDERAL REGISTER].

**ADDRESSES:** You may send comments by any of the following methods:

- Federal eRulemaking Portal: Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- Fax: (202) 493-2251.

- Mail: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE, Washington, DC 20590.

- Hand Delivery: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact HPH spol. s r.o., Čáslavská 126, P.O. Box 112, 284 01 Kutná Hora, Czech Republic, telephone: +420 327 512 633; fax: +420 327 513 441; email: [hph@hph.cz](mailto:hph@hph.cz); Internet: [www.hph.cz](http://www.hph.cz). You may review copies of the referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

### **Examining the AD Docket**

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5527) is in the ADDRESSES section.

Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:** Taylor Martin, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4138; fax: (816) 329-4090; email: [taylor.martin@faa.gov](mailto:taylor.martin@faa.gov).

### **SUPPLEMENTARY INFORMATION:**

#### **Comments Invited**

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the ADDRESSES section.

Include “Docket No. FAA-2012-0598; Directorate Identifier 2012-CE-017-AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

## **Discussion**

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued AD No.: 2012-0073, dated April 30, 2012 (referred to after this as “the MCAI”), to correct an unsafe condition for the specified products. The MCAI states:

A broken elevator control rod in the vertical fin on a Kestrel sailplane has been reported.

The technical investigation revealed that water had soaked into the elevator control rod through a control bore hole and resulted in corrosion damage. The investigation concluded that the corrosion cannot be detected from outside the elevator control rod.

This condition, if not detected and corrected, could lead to failure of the elevator control rod, possibly resulting in loss of control of the sailplane.

To address this unsafe condition, HPH spol. s r.o. published Service Bulletins (SB) : G304CZ-06a), G304CZ17-06a), G304C-06a), providing instructions for elevator control rod inspection and replacement.

For the reasons described above, this AD requires accomplishment of a one-time inspection of the elevator control rod in the vertical fin and replacement with an improved control rod if control rod without drainage hole is used.

You may obtain further information by examining the MCAI in the AD docket.

**Relevant Service Information**

HPH spol.s r.o. has issued Service Bulletin No.: G304CZ – 06 a)\_R01, G304C – 06 a)\_R01, G304CZ17 – 06 a)\_R01, dated April 23, 2012. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

**FAA’s Determination and Requirements of the Proposed AD**

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with this State of Design Authority, they have notified us of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all information and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

**Costs of Compliance**

We estimate that this proposed AD will affect 10 products of U.S. registry. We also estimate that it would take about 6 work-hours per product to comply with the basic requirements of this proposed AD. The average labor rate is \$85 per work-hour. Required parts would cost about \$233 per product.

Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$7,430, or \$743 per product

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. “Subtitle VII: Aviation Programs,” describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in “Subtitle VII, Part A, Subpart III, Section 44701: General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by

prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

### **Regulatory Findings**

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

### **List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### **The Proposed Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

### **PART 39 - AIRWORTHINESS DIRECTIVES**

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

### **§ 39.13 [Amended]**

- 2. The FAA amends § 39.13 by adding the following new AD:

**HPH s. r.o. Sailplanes:** Docket No. FAA-2012-0598; Directorate Identifier 2012-CE-017-AD.

**(a) Comments Due Date**

We must receive comments by [INSERT DATE 45 DAYS AFTER DATE OF PUBLICATION IN THE FEDERAL REGISTER].

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to HPH s. r.o. Models 304C, 304CZ, and 304CZ-17 sailplanes, all serial numbers, certificated in any category.

**(d) Subject**

Air Transport Association of America (ATA) Code 27, Flight controls.

**(e) Reason**

This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as the lack of a drain hole in the elevator control rod, which may allow water to accumulate in the control rod and lead to possible corrosion. We are issuing this AD to prevent failure of the elevator control rod, which could result in loss of control of the sailplane.

**(f) Actions and Compliance**

Unless already done, do the following actions in accordance with HPH spol.s r.o. Service Bulletin No.: G304CZ – 06 a)\_R01, G304C – 06 a)\_R01, G304CZ17 – 06 a)\_R01, dated April 23, 2012:

(1) Within 30 days after the effective date of this AD, inspect the elevator control rod in the vertical fin.

(2) If you find any deficiency during the inspection required by paragraph (f)(1) of this AD, before further flight, replace the elevator control rod with an elevator control rod that has a drain hole.

(3) Within 9 months after the effective date of this AD, unless already done as required by paragraph (f)(2) of this AD, replace the elevator control rod in the vertical fin with an elevator control rod that has a drain hole.

(4) As of the effective date of this AD, do not install an elevator control rod without a drainage hole.

**(g) Other FAA AD Provisions**

The following provisions also apply to this AD:

(1) **Alternative Methods of Compliance (AMOCs):** The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Taylor Martin, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4138; fax: (816) 329-4090; email: [taylor.martin@faa.gov](mailto:taylor.martin@faa.gov). Before using any approved AMOC on any sailplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) **Airworthy Product:** For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) **Reporting Requirements:** For any reporting requirement in this AD, a federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW, Washington, DC 20591, Attn: Information Collection Clearance Officer, AES-200.

**(h) Related Information**

Refer to MCAI European Aviation Safety Agency (EASA) AD No.: 2012-0073, dated April 30, 2012; and HPH spol.s r.o. Service Bulletin No.: G304CZ – 06 a)\_R01, G304C – 06 a)\_R01, G304CZ17 – 06 a)\_R01, dated April 23, 2012, for related information. For service information related to this AD, contact HPH spol. s r.o., Čáslavská 126, P.O. Box 112, 284 01 Kutná Hora, Czech Republic, telephone: +420 327 512 633; fax: +420 327 513 441; email: [hph@hph.cz](mailto:hph@hph.cz); Internet: [www.hph.cz](http://www.hph.cz). You may review copies of the referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

Issued in Kansas City, Missouri, on May 29, 2012.

Earl Lawrence,  
Manager, Small Airplane Directorate,  
Aircraft Certification Service.



[FR Doc. 2012-13563 Filed 06/04/2012 at 8:45 am; Publication Date: 06/05/2012]